

West Warwick - John F. Deering Middle School

June 2017

2 Webster Knight Drive, West Warwick, RI 02893





Introduction

John F. Deering Middle School, located at 2 Webster Knight Drive in West Warwick, Rhode Island, was built in 1971. It comprises 138,600 gross square feet. Each school across the district was visited three times during the Facility Condition Assessments by three teams of specialists in the spring/summer of 2016.

John F. Deering Middle School serves grades 5 - 8, has 50 instructional spaces, and has an enrollment of 1,000. Instructional spaces are defined as rooms in which a student receives education. The LEA reported capacity for John F. Deering Middle School is 1,050 with a resulting utilization of 95%.

For master planning purposes a 5-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For John F. Deering Middle School the 5-year need is \$15,374,324. The findings contained within this report resulted from an assessment of building systems performed by building professionals experienced in disciplines including: architecture, mechanical, plumbing, electrical, acoustics, hazardous materials, and technology infrastructure.



Figure 1: Aerial view of John F. Deering Middle School



West Warwick - John F. Deering Middle School

Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

Discipline Specialists

All assessment teams produced current deficiencies associated with each school. The assessment for the school facilities at the Rhode Island Department of Education included several specialties:

Facility Condition Assessment: Architectural, mechanical, and electrical engineering professionals observed conditions via a visual observation that did not include intrusive measures, destructive investigations, or testing. Additionally, the assessment incorporated input provided by district facilities and maintenance staff where applicable. The assessment team recorded existing conditions, identified problems and deficiencies, documented corrective action and quantities, and identified the priority of the repair in accordance with parameters defined during the planning phase. The team took digital photos at each school to better identify significant deficiencies.

Technology: Technology specialists visited RIDE facilities and met with technology directors to observe and assess each facility's technology infrastructure. The assessment included network architecture, major infrastructure components, classroom instructional systems, necessary building space and support for technology. The technology assessment took into account the desired technology outcome and best practices and processes to ensure results can be attained effectively.

Hazardous Materials: Schools constructed prior to 1990 were assessed by specialists to identify the presence of hazardous materials. The team focused on identifying asbestos containing building materials (ACBMs), lead-based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. If sampling and analysis was required, these activities were recommended but not included in the scope of work.

Traffic: A traffic specialist performed an in-office review of aerial imagery of the traffic infrastructure around the facilities in accordance with section 1.05-7 in the Rhode Island School Construction Regulations and reviewed data collected on site during the facility condition assessment. Based on this information, deficiencies and corrective actions were identified. High problem areas were identified for consideration of more detailed site-specific study and analysis in the future.

Acoustics: Specialists assessed each school's acoustics, including architectural acoustics, mechanical system noise and vibration, and environmental noise. The assessment team evaluated room acoustics with particular attention to the intelligibility of speech in learning spaces, interior and exterior sound isolation, and mechanical system noise and vibration control.

Educational Program Space Assessment: Teams evaluated schools to ensure that that all spaces adequately support the districts educational program. Standards are established for each classroom type or instructional space. Each space is evaluated to determine if it meets those standards and a listing of alterations that should be made to make the space a better environment for teaching and learning was created.



West Warwick - John F. Deering Middle School

System Summaries

The following tables summarize major building systems at the John F. Deering Middle School campus, identified by discipline and building.

<u>Site</u>

The site level systems for this campus include:

Site	Asphalt Parking Lot Pavement			
	Asphalt Roadway Pavement			
	Asphalt Pedestrian Pavement			
	Concrete Pedestrian Pavement			

Building Envelope

The exterior systems for the building(s) at this campus includes:

01 - Main Building:	Ceramic Tile Exterior Wall
	Painted Exterior Wall
	Pre-cast Concrete Panel Exterior Wall
	Aluminum Exterior Windows
	Steel Exterior Entrance Doors
	Overhead Exterior Utility Doors

The roofing for the building(s) at this campus consists of:

01 - Main Building:	Built-Up Roofing With Ballast
101 - Iviaili Bullullig.	Dunt-Op Rooming with banast

Interior

The interior systems for the building(s) at this campus include:

Interior Demountable Partitions
Wood Interior Doors
Overhead Interior Coiling Doors
Interior Door Hardware
Door Hardware
Suspended Acoustical Grid System
Suspended Acoustical Ceiling Tile
Painted Ceilings
Ceramic Tile Wall
Wood Wall Paneling
Interior Wall Painting
Concrete Flooring
Ceramic Tile Flooring
Quarry Tile Flooring
Wood Flooring
Rubber Tile Flooring



West Warwick - John F. Deering Middle School

01 - Main Building:	Vinyl Composition Tile Flooring		
	Carpet		

Mechanical

The mechanical systems for the building(s) at this campus include:

01 - Main Building:	1,275 MBH Cast Iron Water Boiler
	150 MBH Gas Furnace
	400 MBH Gas Furnace
	10 kW Electric Unit Heater
	Finned Wall Radiator
	Pneumatic Heating System Controls
	3 Ton Ductless Split System
	5 Ton Outside Air Cooled Condenser
	5 Ton Condensing Unit
	7.5 Ton Condensing Unit
	Window Units
	15 HP VFD
	25 HP VFD
	2-Pipe Hot Water Hydronic Distribution System
	1 HP or Smaller Pump
	5 HP Pump
	10 HP Pump
	25 HP Pump
	20,000 CFM Interior AHU
	Ductwork
	Large Roof Exhaust Fan
	Small Roof Exhaust Fan
	Wall Exhaust Fan
	Fire Sprinkler System

Plumbing

The plumbing systems for the building(s) at this campus include:

01 - Main Building:	100 Gallon Water Storage Tank
	1,000 Gallon Water Storage Tank
	4" Backflow Preventers
	Gas Piping System
	52 Gallon Electric Water Heater
	100 Gallon Gas Water Heater
	Domestic Water Piping System
	Classroom Lavatories
	Lavatories



West Warwick - John F. Deering Middle School

01 - Main Building:	Mop/Service Sinks
	Refrigerated Drinking Fountain
	Restroom Lavatories
	Showers
	Toilets
	Urinals
	Air Compressor (5 hp)
	15,000 Gallon Underground Fuel Oil Storage Tank

Electrical

The electrical systems for the building(s) at this campus include:

01 - Main Building:	100 kW Emergency Generator
	Solar Panels
	Automatic Transfer Switch
	1,600 Amp Switchgear
	Panelboard - 120/208 100A
	Panelboard - 120/208 225A
	400 Amp Distribution Panel
	600 Amp Distribution Panel
	800 Amp Distribution Panel
	Electrical Disconnect
	Building Mounted Lighting Fixtures
	Canopy Mounted Lighting Fixtures
	Light Fixtures

M•A•P•P•S ©, Jacobs 2017 6



West Warwick - John F. Deering Middle School

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the school's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the school's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following chart summarizes this site's current deficiencies by building system and priority. The listing details current deficiencies including deferred maintenance, functional deficiencies, code compliance, capital renewal, hazardous materials and technology categories.

Table 1: System by Priority

System	1	2	3	4	5	Total	% of Total
Site	-	-	\$57,115	\$345,825	\$416,108	\$819,048	6.56 %
Roofing	-	\$2,483,102	-	-	-	\$2,483,102	19.90 %
Structural	-	-	-	-	-	\$0	0.00 %
Exterior	-	\$674,931	-	\$53,477	\$778,887	\$1,507,295	12.08 %
Interior	-	-	\$3,217,561	\$1,897,954	\$15,977	\$5,131,492	41.13 %
Mechanical	-	\$209,880	\$14,472	-	-	\$224,353	1.80 %
Electrical	\$4,208	-	-	\$14,359	\$23,660	\$42,228	0.34 %
Plumbing	-	-	-	-	\$219,278	\$219,278	1.76 %
Fire and Life Safety	\$56,658	-	-	-	-	\$56,658	0.45 %
Technology	-	-	\$1,836,321	-	-	\$1,836,321	14.72 %
Conveyances	-	-	-	-	-	\$0	0.00 %
Specialties	-	-	\$4,533	\$76,873	\$76,488	\$157,893	1.27 %
Total	\$60,866	\$3,367,913	\$5,130,002	\$2,388,488	\$1,530,399	\$12,477,669	

^{*}Displayed totals may not sum exactly due to mathematical rounding

The building systems with the most need include:

Interior	-	\$5,131,492
Roofing	-	\$2,483,102
Technology	-	\$1,836,321

The chart below represents the building systems and associated deficiency costs.




Figure 2: System Deficiencies



West Warwick - John F. Deering Middle School

Current Deficiencies by Category

Deficiencies have been further grouped according to the observed category.

- Acoustics deficiencies relate to room acoustics, sound insolation, and mechanical systems and vibration control modeled after ANSI/ASA Standard S12.60-2010 and ASHRAE Handbook, Chapter 47 on Sound and Vibration Control.
- Barrier to Accessibility deficiencies relate to the Americans with Disabilities Act and the Rhode Island Governors Commission on Disability. Additional items related to accessibility may be included other categories.
- Capital Renewal items have reached or exceeded serviceable life and require replacement. These are current and do not include life cycle capital renewal forecasts. Also included are deficiencies correcting planned work postponed beyond its regular life expectancy.
- Code Compliance deficiencies related to current codes. Many may fall under grandfather clauses, which allow buildings to continue operating under codes effective at the time of construction. However, there are instances where the level of renovation requires full compliance which are reflected in the master plan.
- Educational Adequacy deficiencies identify where facilities do not align with the Basic Education Program and the RIDE School Construction Regulations.
- Functional Deficiencies are deficiencies for components or systems that have failed before the end of expected life or are not the right application, size, or design.
- Hazardous Materials include deficiencies for building systems or components containing potentially hazardous material. The team focused on identifying asbestos containing building materials (ACBMs), lead based painted (LBP) areas, polychlorinated biphenyls (PCBs), and chlorofluorocarbons (CFCs). As part of an indoor air and exterior air quality assessment, the team noted evidence of mold, water intrusion, mercury, and oil and hazardous materials (OHMs) exposure. With other scopes of work there may be other costs associated with hazardous materials.
- **Technology** deficiencies relate to network architecture, technology infrastructure, classroom systems, and support. Examples of technology deficiencies include: security cameras, secure electronic access, telephone handsets, and dedicated air conditioning for telecommunication rooms.
- Traffic deficiencies relate to vehicle or pedestrian traffic, such as bus loops, crosswalks, and pavement markings.



The following chart and table represent the deficiency category by priority. This listing includes current deficiencies for all building systems.

Table 2: Deficiency Category by Priority

Category	1	2	3	4	5	Total
Acoustics	-	-	-	\$62,389	-	\$62,389
Barrier to Accessibility	-	-	\$148,546	-	-	\$148,546
Capital Renewal	-	\$3,367,913	\$3,140,601	\$2,019,378	\$947,240	\$9,475,132
Code Compliance	-	-	-	-	-	\$0
Educational Adequacy	\$60,866	-	\$100,851	\$57,905	\$583,160	\$802,782
Functional Deficiency	-	-	-	-	-	\$0
Hazardous Material	-	-	-	\$248,815	-	\$248,815
Technology	-	-	\$1,740,003	-	-	\$1,740,003
Traffic	-	-	-	-	-	\$0
Total	\$60,866	\$3,367,913	\$5,130,002	\$2,388,488	\$1,530,399	\$12,477,669

^{*}Displayed totals may not sum exactly due to mathematical rounding




Figure 3: Current deficiencies by priority



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If a need for immediate replacement was identified, a deficiency was created with the estimated repair costs. The identified deficiency contributes to the facility's total current repair costs.

Capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a 5-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following chart shows all current deficiencies and the subsequent 5-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3: Capital Renewal Forecast

			Life Cycle					
System	Current Deficiencies	Year 1 2017	Year 2 2018	Year 3 2019	Year 4 2020	Year 5 2021	LC Yr. 1-5 Total	Total 5-Year Need
Site	\$819,048	\$0	\$0	\$0	\$0	\$0	\$0	\$819,048
Roofing	\$2,483,102	\$0	\$0	\$0	\$0	\$0	\$0	\$2,483,102
Structural	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$1,507,295	\$0	\$0	\$0	\$0	\$0	\$0	\$1,507,295
Interior	\$5,131,492	\$0	\$0	\$550,392	\$0	\$73,565	\$623,957	\$5,755,450
Mechanical	\$224,353	\$0	\$0	\$936,202	\$1,068,355	\$25,950	\$2,030,507	\$2,254,860
Electrical	\$42,228	\$0	\$0	\$0	\$8,271	\$82,102	\$90,373	\$132,601
Plumbing	\$219,278	\$0	\$0	\$0	\$132,793	\$9,245	\$142,038	\$361,316
Fire and Life Safety	\$56,658	\$0	\$0	\$0	\$0	\$0	\$0	\$56,658
Technology	\$1,836,321	\$0	\$0	\$0	\$0	\$0	\$0	\$1,836,321
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$157,893	\$0	\$0	\$0	\$0	\$0	\$0	\$157,893
Total	\$12,477,669	\$0	\$0	\$1,486,594	\$1,209,419	\$190,862	\$2,886,875	\$15,364,544

^{*}Displayed totals may not sum exactly due to mathematical rounding





Figure 4: Life Cycle Capital Renewal Forecast

Facility Condition Index (FCI)

The Facility Condition Index (FCI) is used throughout the facility condition assessment industry as a general indicator of a building's health. Since 1991, the facility management industry has used an index called the FCI to benchmark the relative condition of a group of schools. The FCI is derived by dividing the total repair cost, including educational adequacy and site-related repairs, by the total replacement cost. A facility with a higher FCI percentage has more need, or higher priority, than a facility with a lower FCI. It should be noted that costs in the New Construction category are not included in the FCI calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair schools with a FCI of 65 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCI at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCI is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making school facility decisions.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCI was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCI calculation.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Providence, Rhode Island area. The estimated replacement cost for this facility is \$45,738,000. For planning purposes, the total 5-year need at the John F. Deering Middle School is \$15,374,324 (Life Cycle Years 1-5 plus the FCI deficiency cost). The John F. Deering Middle School facility has a 5-year FCI of 33.59%.




Figure 5: 5-Year FCI

It is important to reiterate that this FCI replacement threshold is not conclusive, but is intended to initiate planning discussion in which other relevant issues with regard to a facility's disposition must be incorporated. This merely suggests where conversations regarding replacement might occur.



West Warwick - John F. Deering Middle School

Rhode Island Aspirational Capacity

The capacity of a school reflects how many students the school's physical facility can effectively serve. There are various methodologies that exist to calculate capacity. It is not uncommon to review an existing building only to find that the capacity that had once been assigned is greater than what can be reasonably accommodated today. This is primarily because of a change in how programs are delivered.

The Rhode Island Aspirational Capacity is based on the Rhode Island School Construction Regulations (SCRs) and is an aspirational goal of space use. The capacity for each individual public school in the state of Rhode Island was designed to conform to Section 1.06-2 Space Allowance Guidelines of the Rhode Island Department of Education (RIDE) SCRs. These regulations outline the allowed gross square feet (GSF) per student at each school type (ES, MS, HS) by utilizing a sliding scale based on projected enrollment. The resulting capacities reflect how school capacities align to the SCRs for new construction. The existing enrollment was multiplied by the GSF per student for the appropriate bracket. For the purposes of this analysis, Pre-K centers were rolled into the elementary totals, and K-8 facilities were counted as middle schools.

The most consistent and equitable way a state can determine school capacities across a variety of districts and educational program offerings is to use square-foot-per-student standards. In contrast, in the 2013 Public Schoolhouse Assessment Report, LEAs self-reported capacities for their elementary, middle and high schools. Districts typically report "functional capacity," which is defined as the number of students each classroom can accommodate. Functional capacity counts how many students can occupy a space, not how much room students and teachers have within that space. For example, a 650-square-foot classroom and a 950-square-foot classroom can both have a reported capacity of 25 students, but the actual teaching and learning space per student varies greatly.

The variation in square feet per student impacts the kinds of teaching practices possible in each space. The lowest allocation of space per student restricts group and project-based learning strategies and requires teachers to teach in more traditional, lecture-style formats, due to a lack of space. Furthermore, the number of students that can be accommodated in a classroom does not account for access to sufficient common spaces such as libraries, cafeterias, and gymnasiums. When cafeterias are undersized relative to the population, schools must host four or more lunch periods a day, resulting in some students eating lunch mid-morning and some mid-afternoon. Similarly, undersized libraries and gymnasiums create scheduling headaches for schools and restrict student access. Finally, a classroom count-only approach to school capacity does not consider the inherent scheduling challenges schools face.

Applying the Rhode Island Aspirational Capacity, a facility of this size could ideally support an enrollment of approximately 762 students.

Facility New Construction

As part of the Educational Program Space Assessment, select core spaces were compared to the RI School Construction Regulations. If it was determined that a facility was in need of square footage related to a cafeteria or library/media center, a cost for additional space was estimated. This cost is not included in the total 5-year need or the 5-year FCI calculation.

The New Construction cost to bring the John F. Deering Middle School cafeteria and/or library/media center to the size prescribed by the SCRs is estimated to be \$1,270,922.



West Warwick - John F. Deering Middle School

Summary of Findings

The John F. Deering Middle School comprises 138,600 square feet and was constructed in 1971. Current deficiencies at this school total \$12,487,449. Five year capital renewal costs total \$2,886,875. The total identified need for the John F. Deering Middle School (current deficiencies and 5-year capital renewal costs) is \$15,374,324. The 5-year FCI is 33.59%.

Table 4: Facility Condition by Building

	Gross Sq Ft	Year Built	Current Deficiencies	LC Yr. 1-5 Total	Total 5 Yr Need (Yr 1-5 + Current Defs)	5-Year FCI
John F. Deering Middle School Totals	138,600	1971	\$12,487,449	\$2,886,875	\$15,374,324	33.59%

^{*}Displayed totals may not sum exactly due to mathematical rounding

The following pages provide a listing of all current deficiencies and 5-year life cycle need and the associated costs, followed by photos taken during the assessment.

Cost Estimating

Cost estimates are derived from local cost estimating expertise and enhanced by industry best practices, historical cost data, and relevance to the Rhode Island region. Costs have been developed from current market rates as of the 2nd quarter in 2016. All costs are based on a replace-in-kind approach, unless the item was not in compliance with national or state regulations or standards.

For planning and budgeting purposes, facility assessments customarily add a soft cost multiplier onto deficiency repair cost estimates. This soft cost multiplier accounts for costs that are typically incurred when contracting for renovation and construction services. Soft costs typically include construction cost factors, such as contractor overhead and profit, as well as labor and material inflation, professional fees, and administrative costs. Based on the Rhode Island School Construction Regulations, a soft cost multiplier of 20% is included on all cost estimates. Other project allowances are included in the cost estimates based on school attributes such as age, location, and historic designation. All stated costs in the assessment report will include soft costs for planning and budgeting purposes. These are estimates, and costs will vary at the time of construction.



Site Level Deficiencies

Site

Site						
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Asphalt Walks Requ	uire Replacement	Capital Renewal	5,347 SF	3	\$57,115	19412
Note:	Asphalt sidewalks are cracked and weathered.					
Asphalt Paving Req	uires Replacement	Capital Renewal	35 CAR	4	\$144,748	19411
Note:	Asphalt roadway pavement is alligatored and deteriorated.					
Asphalt Paving Req	uires Replacement	Capital Renewal	40 CAR	4	\$165,426	19413
Note:	Parking lot asphalt is cracked and weathered.					
Backstops Require	Replacement	Educational Adequacy	1 Ea.	4	\$35,651	28621
Note:	Backstops Require Replacement					
Exterior Basketball	Goals are Required	Educational Adequacy	1 Ea.	5	\$7,308	28823
Note:	Exterior Basketball Goals are Required					
School lacks a com	petition track.	Educational Adequacy	1 Ea.	5	\$408,800	28280
Note:	School lacks a competition track.	Sub Total for System	6 items		\$819,048	
	Out Tatalife	Sub Total for System				
		or School and Site Level	6 items	i	\$819,048	
Building: 0	1 - Main Building					
Roofing						
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
	th Aggregate Ballast Requires Replacement	Capital Renewal	62,685 SF	2	\$2,483,102	
Note:	Original BUR is old and there is evidence of water in the building an	·		2	Ψ2,403,102	13420
Note.	Original bort is old and there is evidence of water in the building an	Sub Total for System	1 items		\$2,483,102	
Foot a mile m		oub rotal for dystern	i itellis	•	ψ2,403,102	
Exterior						
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
The Aluminum Wind	dow Requires Replacement	Capital Renewal	2,312 SF	2	\$407,548	19418
Note:	Single pane windows are poorly functioning. They are scheduled for	r replacement.				
The Metal Exterior [Door Requires Replacement	Capital Renewal	40 Door	2	\$267,384	19416
Note:	Exterior metal doors are old and rusted. They are scheduled to be r	eplaced.				
The Concrete/CMU	Exterior Requires Repair	Capital Renewal	600 LF	4	\$53,477	19415
Note:	Concrete is cracked and spalling in several areas.					
The Exterior Requir	es Painting	Capital Renewal	135,828 SF Wall	5	\$778,887	19414
Note:	Exterior paint is worn, chipped and peeling.					
		Sub Total for System	4 items	•	\$1,507,295	
Interior						
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
	ware Is Not ADA Compliant	Barrier to Accessibility	50 Door	3	\$148,546	
Note:	Non-compliant door hardware should be replaced.					
Location	: Doors between classroom, closets, teacher rooms, main office and	guidance				
	ing Tiles Require Replacement	Capital Renewal	124,740 SF	3	\$1,173,546	19419
Note:	Ceiling tiles are stained, cracked, and sagging.	·				
The Carpet Flooring	Requires Replacement	Capital Renewal	55,440 SF	3	\$1,256,420	19420
Note:	Carpet is worn, stained, and fraying at seams.				. , ,	
	ion Tile Requires Replacement	Capital Renewal	53,478 SF	3	\$639,048	19421
Note:	VCT flooring is chipped and worn with seams lifting in many areas.		,		,	
Ceiling Grid Require		Capital Renewal	124,740 SF	4	\$1,541,124	19431
Note:	Ceiling grid is old, stained, and rusted.		, 0.	•	∓ .,♥ . i , i ⊆ T	. 5 101
	alls Require Repair Or Replacement	Capital Renewal	800 SF	4	\$22,183	10/25
menor Ceramic Wa	and require repair of replacement	Capital Nellewal	Wall	4	ψ ∠ ∠,103	13423
Note:	Ceramic tile walls are chipped and broken.					
	or Damage of 9x9 Asbestos Floor Tile is Present	Hazardous Material	3,348 SF	4	\$99,467	Rollur
J = 2.30.00.0011			-,	•	‡00, .07	
M•A•P•P•S ©. Jaco	hs 2017					

M•A•P•P•S ©, Jacobs 2017 15





Petide process Peti							
Participation Participatio	Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Paramater Para		& Hazardous Material	364	Ea.	4	\$108,142	Rollup
water in active use - children (measurement uni - square feet) Again (probable per 19%) is base legally)- diamaged area of 94, ft. AND NOT in children (measurement uni - linear feet) Hazardous Material 18 LF 4 \$32,80 Rollup accessible area (measurement uni - linear feet) Part (probable per 19%) is base legally)- diamaged area of 94, ft. AND NOT in children accessible area (measurement uni - square feet) Accusational Accusational \$2.515 \$F 4 \$324,90 Rollup accessible area (measurement uni - square feet) Part (probable per 19%) is base legally)- diamaged area of 94, ft. AND NOT in children accessible area (measurement uni - square feet) Accusational Adequate \$68 \$F 4 \$32,30 \$72,00 Note: Classroom Swith Partitions (continued accessible) area (measurement uni - square feet) Educational Adequate (or in Poor Condition. Educational Adequate (or in Poor Condition. \$8,80 \$F 4 \$23,20 \$8,00		Hazardous Material	642	LF	4	\$15,259	Rollup
Account of the part of problem per part of in ordinary of the part of problem per part of in ordinary of part o		Hazardous Material	21	SF	4	\$208	Rollup
Accusation Acc		- Hazardous Material	18	LF	4	\$428	Rollup
Note: Classroome with Partitions Room Lighting Is Inadequate Of In Poor Condition. Educational Adequate		- Hazardous Material	2,515	SF	4	\$24,906	Rollup
Radical land dequate Or in Poor Condition.	Partitions Provide Insufficient Sound Isolation	Acoustics	2,100	SF	4	\$62,389	27820
Adequary Wall/ceiling materials - area < 9 sq. ft. AND in children-accessible area Wall/ceiling materials - large areas (> 10 sq. ft.) of damage & area in active use - children Wall/ceiling materials - large areas (> 10 sq. ft.) of damage & area in active use - children Wall/ceiling materials - large areas (> 10 sq. ft.) of damage & area in active use - children Room lacks appropriate sound control. Wechanical Mechanical Delicionery Category Category Category Note: Heater Shaustsr/Hoods Requires Replacement The Exterior Condenser Requires Replacement The Large Damenter Exhaustsr/Hoods Require Replacement Category Category Quy UoM Priority Repair Cost Repair Co	Note: Classrooms with Partitions						
Mall/ceiling materials - area < 9 sq. ft. AND in children-accessible area Hazardous Material 17 SF 4 \$1.68 Rollup Mull/ceiling materials - large areas (> 10 sq. ft.) of damage & area in active use - children Hazardous Material 24 SF 4 \$2.38 Rollup Classroom Door Requires Vision Panel Adequacy 200 SF 5 \$6.085 Rollup Room lacks appropriate sound control. Reducational Adequacy 200 SF 5 \$6.012 Rollup Room lacks appropriate sound control. Reducational Adequacy 200 SF 5 \$6.012 Rollup Reducational Adequacy 200 SF 2	Room Lighting Is Inadequate Or In Poor Condition.		588	SF	4	\$22,254	Rollup
Mall/ceiling materials - large areas (> 10 sq. ft.) of damage & area in active use - children Hazardous Materials 24 SF 4 \$3.8 Rollup Classroom Door Requires Vision Panel Adequatory 4 Ea. 5 \$9.056 Rollup Room lacks appropriate sound control. Beducational Adequacy Sub Total for System 19 items \$5.511.492 Technology Sub Total for System 19 items \$5.511.492 Technology Sub Total for System S	Vinyl Cove Base Requires Replacement	Capital Renewal	100	LF	4	\$1,188	19427
Educational Adequacy Adequac	Wall/ceiling materials - area < 9 sq. ft. AND in children-accessible area	Hazardous Material	17	SF	4	\$168	Rollup
Adequacy	Wall/ceiling materials - large areas (> 10 sq. ft.) of damage & area in active use - children	Hazardous Material	24	SF	4	\$238	Rollup
Mechanical Mec	Classroom Door Requires Vision Panel		4	Ea.	5	\$9,065	Rollup
Mechanical Delicioncy Category Category Category Capital Renewal 1	Room lacks appropriate sound control.		200	SF	5	\$6,912	Rollup
Deficiency Category Catego		Sub Total for System	19	items		\$5,131,492	
The Exterior Condenser Requires Replacement	Mechanical						
The Exterior Condenser Requires Replacement		Category	Otv	LloM	Priority	Renair Cost	ID
The Fin Tube Water Radiant Heater Requires Replacement Note: Heaters are aged with heavy rust. Capital Renewal 112 Ea. 2 \$195,432 19429 The Large Diametr Exhausts/Hoods Require Replacement Capital Renewal 1 Ea. 3 \$14,472 19429 Electrical Deficiency Category Qty UoM Priority Repair Cost ID Room last power shut—off valves for utilities Adequacy 2 4 \$1,4,208 Rollup Adequacy The Canopy Lighting Requires Replacement Capital Renewal 10 Ea. 4 \$1,4,208 Rollup Adequacy Room Has Insufficient Extrical Outlets Educational Adequacy 48 Ea. 5 \$23,660 Rollup Adequacy Plumbing Deficiency Category Qty UoM Priority Repair Cost ID Plumbing Cauchinal Adequacy 4 Ea. 5 \$4,382 Pollup Adequacy Plumbing Cauchinal Adequacy 2 4 Educational Adequacy 4 Ea. 5 \$4,582 Pollup Adequacy							
Note: Heaters are aged with heavy rust. Capital Renewal sub Total for System 1 E. B. S. S. \$14,472 19423 \$224,353 Electrical Deficiency Category Qty UoM Priority Repair Cost ID Room last power shut-off valves for utilities Educational Adequacy 3 E. S.	·	·					
The Large Diameter Exhausts/Hoods Require Replacement Capital Renewal 1 Ea. 3 \$14,472 \$19423 \$140000 \$140000 \$140000 \$140000 \$140000 \$140000 \$140000 \$140000 \$140000 \$140000 \$140000 \$1400000 \$1400000 \$14000000 \$14000000 \$14000000 \$14000000 \$1400000000 \$14000000000000000000000000000000000000		Capital Nellewal	112	La.	_	ψ130,432	13423
Please P	g ,	Conital Danewal	4	Г.	2	¢4.4.470	10400
Deficiency	The Large Diameter Exhausts/Hoods Require Replacement	·			3		19423
Deficiency		Sub Total for System	3	items		\$224,353	
Room last power shut-off valves for utilities Educational Adequacy Room Jughting Requires Replacement Capital Renewal 10 Ea. 4 \$14,359 19422 Room Has Insufficient Electrical Outlets Educational Adequacy Sub Total for System 3 items \$42,228 Plumbing	Electrical						
Adequacy	Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Room Has Insufficient Electrical Outlets Educational Adequacy Sub Total for System 3 items \$42,228 \$42,22	Room last power shut-off valves for utilities		3	Ea.	1	\$4,208	Rollup
Adequacy Sub Total for System 3 items \$42,228 Plumbing	The Canopy Lighting Requires Replacement	Capital Renewal	10	Ea.	4	\$14,359	19422
Plumbing Deficiency Category Oty UoM Priority Repair Cost ID Room lacks a drinking fountain. Educational Adequacy The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed Adequacy Underground Fuel/Oil Storage Tank Requires Replacement Capital Renewal 1 Ea. 5 \$168,353 22067 Sub Total for System 3 items \$219,278 Fire and Life Safety Deficiency Category Oty UoM Priority Repair Cost ID Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6)	Room Has Insufficient Electrical Outlets		48	Ea.	5	\$23,660	Rollup
Deficiency Category Qty UoM Priority Repair Cost ID Room lacks a drinking fountain. Educational Adequacy 4 Ea. 5 \$4,382 Rollup The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed Underground Fuel/Oil Storage Tank Requires Replacement Educational Adequacy 31 Ea. 5 \$168,353 22067 Underground Fuel/Oil Storage Tank Requires Replacement Capital Renewal 1 Ea. 5 \$168,353 22067 Sub Total for System 3 items \$219,278 \$219,278 Fire and Life Safety Deficiency Category Qty UoM Priority Repair Cost ID Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Educational Adequacy 5 Ea. 1 \$56,658 Rollup Technology Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Interactive White Board Educational Adequacy 17 Ea. 3 \$96,318 Rollup Technology: Campus network switching electronics are antiquated and/or do not meet standards. Technology 264 Ea. 3 \$130,721 18055		Sub Total for System	3	items		\$42,228	
Room lacks a drinking fountain. Educational Adequacy The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed Educational Adequacy Underground Fuel/Oil Storage Tank Requires Replacement Capital Renewal 1 Ea. 5 \$168,353 22067 Sub Total for System Fire and Life Safety Deficiency Category Categ	Plumbing						
Adequacy The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed Adequacy Underground Fuel/Oil Storage Tank Requires Replacement Capital Renewal But Total for System Brire and Life Safety Category Cate	Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Underground Fuel/Oil Storage Tank Requires Replacement Capital Renewal Sub Total for System	Room lacks a drinking fountain.		4	Ea.	5	\$4,382	Rollup
Fire and Life Safety Deficiency Category Ca	The Class Room Lavatories Plumbing Fixtures Are Missing And Should Be Installed		31	Ea.	5	\$46,544	Rollup
Fire and Life Safety Deficiency Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Beducational Adequacy Sub Total for System 1 items \$5 Ea. 1 \$56,658 Rollup \$56,658 Rollup \$50 Ro	Underground Fuel/Oil Storage Tank Requires Replacement	Capital Renewal	1	Ea.	5	\$168,353	22067
Deficiency Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Beducational Adequacy Sub Total for System 1 items Technology Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Interactive White Board Educational Adequacy Technology: Campus network switching electronics are antiquated and/or do not meet standards. Technology Technology: Category Technology: Campus network switching electronics are antiquated and/or do not meet standards.		Sub Total for System	3	items		\$219,278	
Deficiency Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Beducational Adequacy Sub Total for System 1 items Technology Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Interactive White Board Educational Adequacy Technology: Campus network switching electronics are antiquated and/or do not meet standards. Technology Technology: Category Technology: Campus network switching electronics are antiquated and/or do not meet standards.	Fire and Life Safety						
Room lacks shut-off valves for utilities. (International Fuel Gas Code, Section 409.6) Educational Adequacy Sub Total for System 1 items \$5 Ea. 1 \$56,658 Rollup Technology Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Interactive White Board Educational Adequacy Technology: Campus network switching electronics are antiquated and/or do not meet standards.	-	Category	Otv	HoM	Priority	Renair Cost	ID
Adequacy Sub Total for System 1 items \$56,658 Technology Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Interactive White Board Educational Adequacy Technology: Campus network switching electronics are antiquated and/or do not meet standards. Technology Technology: Campus network switching electronics are antiquated and/or do not meet standards.						•	
TechnologyDeficiencyCategoryQtyUoMPriorityRepair CostIDRoom lacks Interactive White BoardEducational Adequacy17 Ea.3\$96,318RollupTechnology: Campus network switching electronics are antiquated and/or do not meet standards.Technology264 Ea.3\$130,72118055	Noom lacks shut-on valves for diffiles. (international Fuel Gas Code, Section 409.0)		3	La.	ı	φ30,038	Koliup
Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Interactive White Board Educational Adequacy Technology: Campus network switching electronics are antiquated and/or do not meet standards. Technology		Sub Total for System	1	items		\$56,658	
Deficiency Category Qty UoM Priority Repair Cost ID Room lacks Interactive White Board Educational Adequacy Technology: Campus network switching electronics are antiquated and/or do not meet standards. Technology	Technology						
Room lacks Interactive White Board Educational Adequacy Technology: Campus network switching electronics are antiquated and/or do not meet standards. Educational Adequacy Technology: 264 Ea. 3 \$130,721 18055		Category	Qtv	UoM	Priority	Repair Cost	ID
Technology: Campus network switching electronics are antiquated and/or do not meet Technology 264 Ea. 3 \$130,721 18055 standards.		Educational					
Technology: Classroom AV/Multimedia systems are in need of improvements. Technology 50 Ea. 3 \$495,155 18065			264	Ea.	3	\$130,721	18055
	Technology: Classroom AV/Multimedia systems are in need of improvements.	Technology	50	Ea.	3	\$495,155	18065





Technology						
Deficiency	Category	Qty l	JoM	Priority	Repair Cost	ID
Technology: Classroom AV/Multimedia systems are inadequate and/or near end of useful life.	Technology	1 E	≣a.	3	\$20,797	18066
Technology: Instructional spaces do not have local sound reinforcement.	Technology	51 E	≣a.	3	\$252,529	18070
Technology: Intermediate Telecommunications Room grounding system is inadequate or non-existent.	Technology	1 E	≣a.	3	\$5,546	18060
Technology: Intermediate Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1 E	≣а.	3	\$4,952	18062
Technology: Main Telecommunications Room UPS does not meet standards, is inadequate, or non-existent.	Technology	1 E	≣а.	3	\$9,408	18058
Technology: Network cabling infrastructure is outdated (Cat 5 or less) and/or does not meet standards.	Technology	401 E	≣а.	3	\$178,701	18056
Technology: Network system inadequate and/or near end of useful life	Technology	3 E	≣а.	3	\$23,767	18068
Technology: Network system inadequate and/or near end of useful life	Technology	45 E	≣a.	3	\$222,820	18069
Technology: PA/Bell/Clock system is inadequate and/or near end of useful life.	Technology	138,600 \$	SF	3	\$247,062	18067
Technology: Special Space AV/Multimedia system is inadequate.	Technology	1 E	≣a.	3	\$56,448	18064
Technology: Telecommunications Room (large size room) needs dedicated cooling system improvements.	Technology	1 E	≣а.	3	\$7,922	18059
Technology: Telecommunications Room (small size room) needs dedicated cooling system improvements.	Technology	1 E	≣а.	3	\$4,952	18061
Technology: Telephone handsets are inadequate and sparsely deployed throughout the campus.	Technology	50 E	≣a.	3	\$79,225	18063
	Sub Total for System	16 i	tems		\$1,836,321	
Specialties						
Deficiency	Category	Qty l	JoM	Priority	Repair Cost	ID

	Sub Total for System	16 items		\$1,836,321	
Specialties	•				
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Room has insufficient writing area.	Educational Adequacy	1 Ea.	3	\$4,533	Rollup
The Metal Student Lockers Require Replacement	Capital Renewal	150 Ea.	4	\$76,873	19430
Location: First floor corridor and lockers in girls showers					
Room lacks an appropriate refrigerator.	Educational Adequacy	9 Ea.	5	\$76,488	Rollup
	Sub Total for System	3 items		\$157,893	
	Sub Total for Building 01 - Main Building	53 items		\$11,658,621	
	Total for Campus	59 items		\$12,477,669	



John F. Deering Middle School - Life Cycle Summary Yrs 1-5

Building: 01 - Main Building

Interior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)		83,300	SF	\$550,392	3
Suspended Plaster and	Painted ceilings		2,772	SF	\$11,595	5
Wall Paneling	Wood Panel wall		6,790	SF	\$61,970	5
		Sub Total for System	3	items	\$623,957	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Heating System Supplementary Components	Controls - Pneumatic (Bldg.SF)		138,600	SF	\$936,202	3
Facility Hydronic Distribution	2-Pipe Water System (Hot)		138,600	SF	\$1,068,355	4
Decentralized Cooling	Condensing Unit (7.5 Ton)		1	Ea.	\$14,593	5
Decentralized Cooling	Condensing Unit (5 Ton)		1	Ea.	\$11,357	5
		Sub Total for System	4	items	\$2,030,507	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)		6	Ea.	\$8,271	4
Electrical Service	Switchgear - Main Dist Panel (1600 Amps)		1	Ea.	\$82,102	5
		Sub Total for System	2	items	\$90,373	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain		18	Ea.	\$132,793	4
Domestic Water Equipment	Backflow Preventers - 4 in. (Ea.)		1	Ea.	\$9,245	5
		Sub Total for System	2	items	\$142,038	
	Sub Total for	Building 01 - Main Building	11	items	\$2,886,876	
	Total for: Joh	n F. Deering Middle School	11	items	\$2,886,876	



Supporting Photos



Exterior Finishes



Chipped Exterior Paint



Spalling And Cracked Concrete



Peeling Exterior Paint








Cracked Asphalt Sidewalk



Spalling On Pier



Rusted Exterior Door



Alligatored Asphalt Roadway



Site Aerial



Cracked Asphalt Paving







Wood Shop




Main Enrty



Typical Classroom



Cafeteria




Music Room



Band Room

M•A•P•P•S ©, Jacobs 2017 21







Cooking Room



Science Room



Gymnasium



North Elevation




Library



Northwest Elevation

M*A*P*P*S ©, Jacobs 2017







Weight Room



Northwest Elevation



Gymnasium



Toilet Partitions



Art Room



Damaged Ceiling Tiles

M•A•P•P•S ©, Jacobs 2017 23







Peeling Exterior Paint



Worn Carpet



Stained Ceiling Tiles



Chipped VCT



Worn Carpet




Heavily Rusted Exhaust









Broken Ceramic Wall Tile



Non-Compliant Door Hardware



Peeling Vinyl Cove Base



Built-Up Roof



Old And Damaged Lockers



West Warwick - John F. Deering Middle School



Weathered Condensing Unit



Exterior Metal Door



Stained Ceiling Grid

M*A*P*P*S ©, Jacobs 2017 26